




BBI (DBCT) Management Pty Ltd – DBCT 7X Project



COMMUNITY BULLETIN No. 17

Monday 26th February 2007

HAY POINT ROAD CHANGED TRAFFIC CONDITIONS

For your information:-

Now that the first half of the third inloading conveyor under-pass is complete, the Hay Point Road will revert to its original straight line condition as of Tuesday 27th February 2007. Upgrading of the road service is in progress.

Water-filled barriers will be maintained on each side of the road and the speed limit will remain at 40 kilometres per hour as construction work will be carried out on either side of the road.

BBI (DBCT) Management Pty Ltd would like to thank all Hay Point Road users for their patience during the period that the by-pass road was in place.

BBI (DBCT) MANAGEMENT PTY LTD



***For further enquiries contact
Frank Ross on 0419 995 636***